09/4/9439

## UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO.

: 6,839,833 B1

Page 1 of 1

DATED

: January 4, 2005

INVENTOR(S): Thomas D. Hartnett, John S. Kuslak and Leroy J. Longworth

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Title page,

Item [54], Title, the terms "PIPELINE DEPTH CONTROLLER FOR AN INSTRUCTION PROCESSOR" should read -- SYSTEM AND METHOD FOR CONTROLLING THE ENTRY OF INSTRUCTIONS INTO A PIPELINE OF AN **INSTRUCTION PROCESSOR --.** 

Column 24,

Line 2, the terms "pipeline-including" should read -- pipeline including --

Signed and Sealed this

Twelfth Day of April, 2005

JON W. DUDAS Director of the United States Patent and Trademark Office